RICHARD GOODE AEROBATICS

Rhodds Farm, Lyonshall, Hereford, HR5 3LW, UK Tel: +44 (0)1544 340120 Fax: +44 (0)1544 340129

e-mail: richard.goode@russianaeros.com

www.russianaeros.com

WORLD LEADERS IN RUSSIAN SPORTING AIRCRAFT & ENGINES

In partnership with Aerometal Kft, Hungary

Price List 2020

- Typically, all overhauled components will receive an EASA "form 1" document – the highest European qualification for an aviation component.
- "Core exchange" prices are those we offer for an old component/ancillary that is worn, but complete and not damaged.
- Core exchange parts MUST be sent to Aerometal at the following address: Marcell Marczy, Aerometal Kft., Ipari Park HRSZ:3508/19, Asboth Oszkar utca 4., 2038 Soskut, Hungary, Tel. +36706763869. Please DO NOT send them to us at Rhodds Farm.
- Prices in Euros unless otherwise stated, but we have an easy and cheap way for you to pay in your currency and we get paid in Euros.
- With every component/ancillary that requires gaskets or extra fitting parts for installation, these are always included
- Prices are net and we may need to add VAT if we are selling to private customers in Europe who are not registered for EU VAT

Electrical: M14P/PF & AI14

Part	Price	Core Exchange
M9F & M-9 magneto. Totally overhauled with new bearing, new coil,		
new points, and new "pencil". According to conventional Russian practise, we do not include the magneto cap — the Bakelite disc into		
which the plug leads are fitted – as this is part of the ignition system.		
We do have supplies of these, please see below	€1,220.00	€230.00
M9 – 35M magneto. Totally overhauled, as the M9F magneto (above),		
plus the additional overhaul of the complex counterweight		
mechanism	€1,280.00	€230.00
Points. Finally, we are making our own points. Very high quality and		
machine-tested for over 2,000 hours!!	€220.00	
Coil. We have made a significant investment to design and produce		
dramatically improved coils, and, critically, with an external		

through heat and age. Importantly these coils are now fully certified by UK CAA and EASA, who control all aviation in Europe. They are unconditionally guaranteed for five years, but we conservatively expect them to last at least 20 years. Additionally, as part of the testing programme, it has been demonstrated that the spark is 20% stronger than with a standard coil, leading to easier starting; less plug-fouling and smoother running. Magneto "pencil" Magneto rotors. New manufacture, using improved materials and extensively tested Magneto cap. New manufacture, using improved materials and extensively tested Magneto cap. New manufacture, using improved materials and extensively tested Magneto cap. New manufacture, using improved materials and extensively tested Magneto to cap. New manufacture, using improved materials and extensively tested Magneto to cap. New manufacture, using improved materials and extensively tested Magneto to cap. New manufacture, using improved materials and extensively tested Magneto to cap. New manufacture, using improved materials and extensively tested Magneto to cap. New manufacture, using improved materials and extensively tested Electrics to apply tested Electrics to start conversion kit. Our new kit with the "Thunderbolt" very low resistance leads, improving performance and limiting radio interference. Also includes the much improved modifications from Aerometal. Totally complete with everything needed, including latest NGK spark plugs. Approved by EASA; UK CAA and French DGAC Electric start conversion. Cost when fitted to an engine during overhaul. Electronic ignition. Net cost if fitted to an engine undergoing overhaul. US\$9200.00 Electronic ignition. Net cost if fitted to an engine undergoing overhaul. U\$\$9200.00 Electronic ignition. Net cost if fitted to an engine undergoing overhaul. Overhaul Overhau		l	
by UK CAA and EASA, who control all aviation in Europe. They are unconditionally guaranteed for five years, but we conservatively expect them to last at least 20 years. Additionally, as part of the testing programme, it has been demonstrated that the spark is 20% stronger than with a standard coil, leading to easier starting; less plug-fouling and smoother running. Magneto "pencil" Magneto orbors. New manufacture, using improved materials and extensively tested Magneto cap. New manufacture, using improved materials and extensively tested E115.00 Isolator Automotive plug conversion kit. Our new kit with the "Thunderbolt" very low resistance leads, improving performance and limiting radio interference. Also includes the much improved modifications from Aerometal. Totally complete with everything needed, including latest NGK spark plugs. Approved by EASA; UK CAA and French DGAC Electric start conversion. Cost when fitted to an engine during overhaul. Electronic ignition. Net cost if fitted to an engine undergoing overhaul. Tacho-generator Overhaul Price Core Exchange M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 Magneto check. Physical check, individual test of components and	capacitor which gets over the historic problems of capacitor failure		
unconditionally guaranteed for five years, but we conservatively expect them to last at least 20 years. Additionally, as part of the testing programme, it has been demonstrated that the spark is 20% stronger than with a standard coil, leading to easier starting; less plug-fouling and smoother running. Magneto "pencil" Magneto rotors. New manufacture, using improved materials and extensively tested Magneto cap. New manufacture, using improved materials and extensively tested Magneto cap. New manufacture, using improved materials and extensively tested E135.00 Automotive plug conversion kit. Our new kit with the "Thunderbolt" very low resistance leads, improving performance and limiting radio interference. Also includes the much improved modifications from Aerometal. Totally complete with everything needed, including latest NGK spark plugs. Approved by EASA; UK CAA and French DGAC Electric start conversion. Cost when fitted to an engine during overhaul. Electronic ignition. Net cost if fitted to an engine undergoing overhaul. Tacho-generator Overhaul Price Core Exchange M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 Coil Magneto check. Physical check, individual test of components and			
expect them to last at least 20 years. Additionally, as part of the testing programme, it has been demonstrated that the spark is 20% stronger than with a standard coil, leading to easier starting; less plug-fouling and smoother running. Magneto "pencil" Magneto rotors. New manufacture, using improved materials and extensively tested Magneto cap. New manufacture, using improved materials and extensively tested Solator Automotive plug conversion kit. Our new kit with the "Thunderbolt" very low resistance leads, improving performance and limiting radio interference. Also includes the much improved modifications from Aerometal. Totally complete with everything needed, including latest NGK spark plugs. Approved by EASA; UK CAA and French DGAC Electric start conversion. Cost when fitted to an engine during overhaul. Electronic ignition. Net cost if fitted to an engine undergoing overhaul. Tacho-generator Overhaul M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional £145 and of course we will return the cracked rotor with the magneto. Solution (1990.00) €230.00 Magneto check. Physical check, individual test of components and			
testing programme, it has been demonstrated that the spark is 20% stronger than with a standard coil, leading to easier starting; less plug-fouling and smoother running. Magneto "pencil" Magneto rotors. New manufacture, using improved materials and extensively tested Magneto cap. New manufacture, using improved materials and extensively tested E115.00 Magneto cap. New manufacture, using improved materials and extensively tested E135.00 Isolator Automotive plug conversion kit. Our new kit with the "Thunderbolt" very low resistance leads, improving performance and limiting radio interference. Also includes the much improved modifications from Aerometal. Totally complete with everything needed, including latest NGK spark plugs. Approved by EASA; UK CAA and French DGAC Electric start conversion. Cost when fitted to an engine during overhaul. Electronic ignition. Net cost if fitted to an engine undergoing overhaul. Tacho-generator Overhaul Price Core Exchange M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 Coil Magneto check. Physical check, individual test of components and			
stronger than with a standard coil, leading to easier starting; less plug-fouling and smoother running. Magneto "pencil" E80.00 Magneto rotors. New manufacture, using improved materials and extensively tested Magneto cap. New manufacture, using improved materials and extensively tested E115.00 Isolator Automotive plug conversion kit. Our new kit with the "Thunderbolt" very low resistance leads, improving performance and limiting radio interference. Also includes the much improved modifications from Aerometal. Totally complete with everything needed, including latest NGK spark plugs. Approved by EASA; UK CAA and French DGAC Electric start conversion. Cost when fitted to an engine during overhaul. Electronic ignition. Net cost if fitted to an engine undergoing overhaul. US\$9200.00 Tacho-generator Overhaul Price Core Exchange M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 €400.00 Magneto check. Physical check, individual test of components and	expect them to last at least 20 years. Additionally, as part of the		
Plug-fouling and smoother running. €430.00 Magneto "pencil" €80.00 Magneto rotors. New manufacture, using improved materials and extensively tested €115.00 Magneto cap. New manufacture, using improved materials and extensively tested €135.00 Isolator €65.00 Automotive plug conversion kit. Our new kit with the "Thunderbolt" very low resistance leads, improving performance and limiting radio interference. Also includes the much improved modifications from Aerometal. Totally complete with everything needed, including latest NGK spark plugs. Approved by EASA; UK CAA and French DGAC €595.00 Electric start conversion. Cost when fitted to an engine during overhaul. €3,300.00 Electronic ignition. Net cost if fitted to an engine undergoing overhaul. U\$\$9200.00 Tacho-generator €540.00 €130.00 Tacho-generator €540.00 €230.00 Overhaul Price Core Exchange	testing programme, it has been demonstrated that the spark is 20%		
Magneto "pencil" €80.00 Magneto rotors. New manufacture, using improved materials and extensively tested €115.00 Magneto cap. New manufacture, using improved materials and extensively tested €135.00 Isolator €65.00 Automotive plug conversion kit. Our new kit with the "Thunderbolt" very low resistance leads, improving performance and limiting radio interference. Also includes the much improved modifications from Aerometal. Totally complete with everything needed, including latest NGK spark plugs. Approved by EASA; UK CAA and French DGAC €595.00 Electric start conversion. Cost when fitted to an engine during overhaul. €3,300.00 €3,300.00 Electronic ignition. Net cost if fitted to an engine undergoing overhaul. US\$9200.00 €130.00 Tacho-generator €540.00 €130.00 Overhaul Price Core Exchange M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. €990.00 €230.00 M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 €1,050.00 Coil €400.00	stronger than with a standard coil, leading to easier starting; less		
Magneto rotors. New manufacture, using improved materials and extensively tested €115.00 Magneto cap. New manufacture, using improved materials and extensively tested €135.00 Isolator €65.00 Automotive plug conversion kit. Our new kit with the "Thunderbolt" very low resistance leads, improving performance and limiting radio interference. Also includes the much improved modifications from Aerometal. Totally complete with everything needed, including latest NGK spark plugs. Approved by EASA; UK CAA and French DGAC €595.00 Electric start conversion. Cost when fitted to an engine during overhaul. €3,300.00 Electronic ignition. Net cost if fitted to an engine undergoing overhaul. U\$\$9200.00 Tacho-generator €540.00 M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. €990.00 €230.00 M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 €1,050.00 Coil €400.00	plug-fouling and smoother running.	€430.00	
extensively tested €115.00 Magneto cap. New manufacture, using improved materials and extensively tested €135.00 Isolator €65.00 Automotive plug conversion kit. Our new kit with the "Thunderbolt" very low resistance leads, improving performance and limiting radio interference. Also includes the much improved modifications from Aerometal. Totally complete with everything needed, including latest NGK spark plugs. Approved by EASA; UK CAA and French DGAC €595.00 Electric start conversion. Cost when fitted to an engine during overhaul. €3,300.00 Electronic ignition. Net cost if fitted to an engine undergoing overhaul. US\$9200.00 Tacho-generator €540.00 €130.00 Overhaul Price Core Exchange M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. €990.00 €230.00 M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 €1,050.00 Coil €400.00	Magneto "pencil"	€80.00	
Magneto cap. New manufacture, using improved materials and extensively tested €135.00 Isolator €65.00 Automotive plug conversion kit. Our new kit with the "Thunderbolt" very low resistance leads, improving performance and limiting radio interference. Also includes the much improved modifications from Aerometal. Totally complete with everything needed, including latest NGK spark plugs. Approved by EASA; UK CAA and French DGAC €595.00 Electric start conversion. Cost when fitted to an engine during overhaul. €3,300.00 Electronic ignition. Net cost if fitted to an engine undergoing overhaul. U\$\$9200.00 Tacho-generator €540.00 E130.00 Overhaul Price M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. €990.00 M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 Coil €400.00	Magneto rotors. New manufacture, using improved materials and		
Extensively tested €135.00	extensively tested	€115.00	
Isolator Automotive plug conversion kit. Our new kit with the "Thunderbolt" very low resistance leads, improving performance and limiting radio interference. Also includes the much improved modifications from Aerometal. Totally complete with everything needed, including latest NGK spark plugs. Approved by EASA; UK CAA and French DGAC Electric start conversion. Cost when fitted to an engine during overhaul. Electronic ignition. Net cost if fitted to an engine undergoing overhaul. Tacho-generator Overhaul Price Core Exchange M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 Coil Automotive plug conversion kit. Our new kit with the "Thunderbolt" €550.00 €130.00 €130.00 €230.00 Augneto check. Physical check, individual test of components and	Magneto cap. New manufacture, using improved materials and		
Automotive plug conversion kit. Our new kit with the "Thunderbolt" very low resistance leads, improving performance and limiting radio interference. Also includes the much improved modifications from Aerometal. Totally complete with everything needed, including latest NGK spark plugs. Approved by EASA; UK CAA and French DGAC Electric start conversion. Cost when fitted to an engine during overhaul. Electronic ignition. Net cost if fitted to an engine undergoing overhaul. US\$9200.00 Tacho-generator Price Core Exchange M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 Coil €400.00	extensively tested	€135.00	
very low resistance leads, improving performance and limiting radio interference. Also includes the much improved modifications from Aerometal. Totally complete with everything needed, including latest NGK spark plugs. Approved by EASA; UK CAA and French DGAC €595.00 Electric start conversion. Cost when fitted to an engine during overhaul. €3,300.00 Electronic ignition. Net cost if fitted to an engine undergoing overhaul. U\$\$9200.00 Tacho-generator €540.00 €130.00 Overhaul Price Core Exchange M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. €990.00 €230.00 M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 Coil €400.00 Magneto check. Physical check, individual test of components and	Isolator	€65.00	
interference. Also includes the much improved modifications from Aerometal. Totally complete with everything needed, including latest NGK spark plugs. Approved by EASA; UK CAA and French DGAC €595.00 Electric start conversion. Cost when fitted to an engine during overhaul. €3,300.00 Electronic ignition. Net cost if fitted to an engine undergoing overhaul. US\$9200.00 Tacho-generator €540.00 M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. €990.00 M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 Coil €400.00 Magneto check. Physical check, individual test of components and	Automotive plug conversion kit. Our new kit with the "Thunderbolt"		
interference. Also includes the much improved modifications from Aerometal. Totally complete with everything needed, including latest NGK spark plugs. Approved by EASA; UK CAA and French DGAC €595.00 Electric start conversion. Cost when fitted to an engine during overhaul. €3,300.00 Electronic ignition. Net cost if fitted to an engine undergoing overhaul. US\$9200.00 Tacho-generator €540.00 M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. €990.00 M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 Coil €400.00 Magneto check. Physical check, individual test of components and	very low resistance leads, improving performance and limiting radio		
Aerometal. Totally complete with everything needed, including latest NGK spark plugs. Approved by EASA; UK CAA and French DGAC €595.00 Electric start conversion. Cost when fitted to an engine during overhaul. €3,300.00 Electronic ignition. Net cost if fitted to an engine undergoing overhaul. US\$9200.00 Tacho-generator €540.00 Electronic ignition. Net cost if fitted to an engine undergoing overhaul. US\$9200.00 Tacho-generator €540.00 Electronic ignition. Net cost if fitted to an engine undergoing overhaul. US\$9200.00 Tacho-generator €540.00 Electronic ignition. Net cost if fitted to an engine undergoing overhaul. US\$9200.00 Tacho-generator €540.00 M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. €990.00 €230.00 M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 €1,050.00 Coil €400.00 Magneto check. Physical check, individual test of components and €400.00			
NGK spark plugs. Approved by EASA; UK CAA and French DGAC €595.00 Electric start conversion. Cost when fitted to an engine during overhaul. €3,300.00 Electronic ignition. Net cost if fitted to an engine undergoing overhaul. US\$9200.00 Tacho-generator €540.00 €130.00 Overhaul M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. €990.00 €230.00 M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 €1,050.00 Coil €400.00 Magneto check. Physical check, individual test of components and €3,300.00			
Electric start conversion. Cost when fitted to an engine during overhaul. Electronic ignition. Net cost if fitted to an engine undergoing overhaul. U\$\$9200.00 Tacho-generator Core Exchange M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 Magneto check. Physical check, individual test of components and	NGK spark plugs. Approved by EASA; UK CAA and French DGAC	€595.00	
Electronic ignition. Net cost if fitted to an engine undergoing overhaul. Tacho-generator Core Exchange M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism Coil Magneto check. Physical check, individual test of components and			
overhaul. US\$9200.00 Tacho-generator €540.00 Overhaul Price Core Exchange M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. €990.00 €230.00 M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 €400.00 Magneto check. Physical check, individual test of components and €400.00	overhaul.	€3,300.00	
Tacho-generator Overhaul Price Core Exchange M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 Coil Magneto check. Physical check, individual test of components and	Electronic ignition. Net cost if fitted to an engine undergoing		
Overhaul Price Core Exchange M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. €990.00 €230.00 M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 €400.00 Coil €400.00 Magneto check. Physical check, individual test of components and €400.00	overhaul.	US\$9200.00	
Overhaul Price Exchange M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. €990.00 €230.00 M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 €1,050.00 Coil €400.00 Magneto check. Physical check, individual test of components and Fixehange	Tacho-generator	€540.00	€130.00
Overhaul Price Exchange M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto. €990.00 €230.00 M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 €400.00 Coil €400.00 Magneto check. Physical check, individual test of components and €400.00			
M9F & M-9 magneto. Totally overhauled with new bearing, new coil, new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto.	Overhaul	Price	Core
new points and new "pencil". On occasions, we need to change the rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto.	Overnaui	File	Exchange
rotor. If we do, we charge an additional €145 and of course we will return the cracked rotor with the magneto.€990.00€230.00M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism€1,050.00Coil€400.00Magneto check. Physical check, individual test of components and	M9F & M-9 magneto. Totally overhauled with new bearing, new coil,		
return the cracked rotor with the magneto. €990.00 €230.00 M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 Coil €400.00 Magneto check. Physical check, individual test of components and	new points and new "pencil". On occasions, we need to change the		
M9-35M magneto. As the M9F magneto (above), plus overhauling the complex counterweight mechanism €1,050.00 Coil €400.00 Magneto check. Physical check, individual test of components and	rotor. If we do, we charge an additional €145 and of course we will		
the complex counterweight mechanism €1,050.00 Coil €400.00 Magneto check. Physical check, individual test of components and	return the cracked rotor with the magneto.	€990.00	€230.00
Coil €400.00 Magneto check. Physical check, individual test of components and	M9-35M magneto. As the M9F magneto (above), plus overhauling		
Magneto check. Physical check, individual test of components and	the complex counterweight mechanism	€1,050.00	
	Coil	€400.00	
then 2 hour test in high-temperature test cell; new paperwork. €290.00	Magneto check. Physical check, individual test of components and		
, , , ,	then 2 hour test in high-temperature test cell; new paperwork.	€290.00	
Tacho-generator €410.00	Tacho-generator	€410.00	

Fuel System: M14P/PF & Al14

Part	Price	Core Exchange
Carburettor AK14P & K-14A. Zero-timed. We do not include the composite gasket for installation of the carburettor, since these are almost always reusable. But an additional one can be included for		
€80.	€890.00	€230.00
Carburettor membranes (2) for M 14 and AI 14 engines	€195.00	
Suction jets, each. Sizes 0.8mm to 1.9mm.	€17.00	
Acceleration jets, each. Sizes 0.6mm to 0.9mm	€17.00	

Part	Price	Core Exchange
Fuel pump 702ML (for M14) & 702M (for Al14). Zero-timed.	€320.00	€95.00
Fuel pump membrane.	€70.00	
Overhaul	Price	Core Exchange
Carburettor AK14P & K-14A . Including new membranes; mechanical overhaul; new paint. We do not include the composite gasket for installation of the carburettor, since these are almost always reusable. But an additional one can be included for €60.	€660.00	
Carburettor check. To check an unused carburettor, including new membranes and test bench session.	€390.00	
Fuel pump 702ML & 702M. Please see below for price for internal blades	€225.00	
Fuel pump internal blades (4). Replaced during overhaul if originals not useable	€100.00	

Cylinders: M14P/PF& Al14

Part	Price	Core Exchange
Cylinders. Used, complete, with valves, valve gear, etc.	€800.00	
Set of gaskets for reinstalling all 9 cylinders	€345.00	
New exhaust valves	€210.00	€30.00
Overhauled exhaust valves. Hard chromed stem to new dimensions & new "seat".	€135.00	€30.00
Overhauled inlet valves. Good condition and to correct dimensions	€110.00	€20.00
Valve guide	€115.00	
Valve cover gasket	€4.00	
Valve cover wire	€12.00	
Set of 5 new Russian piston rings	€160.00	
M14P R1 Russian pistons. Set, complete with rings, pins and plugs.	€3,180	
SPC pistons. Set, complete with rings, pins and plugs.	€2,980.00	
Barrett Pistons. Set, complete with rings, pins and plugs.	€3,590.00	
Exhaust nuts each	€45.00	
Exhaust Olive (gasket), standard size, 10mm thick	€28.00	
Exhaust Olive, special size, any thickness	€38.00	
Intake tube gaskets	€4.00	
Set of exhaust clamps (7)	€690.00	
Exhaust stub. About 8cms	€20.00	
Connecting rod	€245.00	
Big manifold oil drain plugs, for fitting oil drain system	€42.00	
Air start valves, totally overhauled	€95.00	
Air start pipe (from distributor to air start valve). Fully checked and nickel plated	€40.00	
New baffle "pads", including rivets to attach to baffles	€30.00	

Overhaul	Price	Core Exchange
Cylinders, price per cylinder. <i>Including honing; fitting pistons;</i> overhauled valves; new valve oil seal; new heat resistant paint, etc.	€1,020.00	
Honing (per cylinder)	€135.00	
Exhaust valves. Hard chromed stem to new dimensions & new "seat"	€160.00	

Ancillaries: M14P/PF & AI14

Part	Price	Core Exchange
Compressor AK-50A & AK-50P12, zero-timed. <i>Including new pistons</i>		
and cylinders if not to new tolerances.	€1,060.00	€190.00
Compressor drive coupling	€80.00	€40.00
Compressor air filter & retaining clip	€7.00	
Air compressor gasket	€5.00	
Propeller governor. R2	€495.00	€165.00
Oil cooler. Standard Yak and Sukhoi.	€1,050.00	€225.00
Large oil cooler. 50% more cooling capacity. Same fittings as standard. Used but fully overhauled.	€950.00	
Oil pump MM-14A. Zero-timed.	€380.00	€95.00
Airstart distributor	€280.00	€85.00
Generator GSR-3000 & GSK-1500M	€705.00	€145.00
Overhaul	Price	Core Exchange
Generator GSR-3000 & GSK-1500M	€560.00	
Compressor AK-50A & AK-50P12. Total overhaul including new		
pistons and cylinders if not to new tolerances.	€870.00	
Compressor drive coupling	€40.00	
Propeller governor. R2	€330.00	
Oil cooler. Standard Yak and Sukhoi.	€650.00	
Oil pump	€225.00	
Airstart distributor	€165.00	
Air bottle pressure testing. <i>Including x-ray and crack test; boroscope inspection; electronic measurement of precise wall thickness (results given); pressure test to 100 bar; recertification and EASA form 1.</i>	€205.00	

Gearbox & Pyramid: M14P/PF & Al14

Part	Price	Core Exchange
New propeller shaft/flange. Russian or SAE. Core exchange price only		
if corrosion does not prevent overhaul.	€900.00	€250.00
Overhauled propeller shaft/flange. Russian or SAE. Core exchange		
price only if corrosion does not prevent overhaul.	€600.00	€250.00
Uprated MT governor springs (2). For better aerobatic performance	€30.00	
Gearbox oil seal rings	€76.00	

Part	Price	Core Exchange
Gearbox satellite gear, each	€146.00	
Micro-polishing gears in drive gearbox and ancillary/supercharger		
gearbox	€600.00	
Propeller adapter. Russian engine to SAE prop	€650.00	
Reverse adapter. SAE engine to Russian prop	€650.00	
Gearbox, after total overhaul	€3,250.00	€1,850.00
Overhaul	Price	Core Exchange
Gearbox painting and new data plate	€295.00	
Ground-strike: full shock load test and inspection	€925.00	
Gearbox total overhaul	€1,400.00	
Full ground-strike test and inspection, for both gearbox and "pyramid" – supercharger and all accessory drives	€1,850.00	
Ground-strike: dismantling, inspection, disassembly of gearbox, pyramid, crankcase, cylinders and 3 hour dynonometer test run. But excluding any repair	€5,800.00	
Ground-strike: total disassembly, total inspection and x-ray, reface valves, inspect and test all ancillaries, 3 hour test run. But excluding any repair	€6,900.00	
Prop shaft/flange overhaul	€360.00	
Pyramid overhaul: overhaul of complete "pyramid"; supercharger; accessory case; accessory gearbox	€2,950.00	€1,100.00
Pyramid total overhaul and conversion to PF specification.	€6,450.00	€1,100.00
Additional cost of converting engine to "PF" specification during overhaul	€3,500.00	

Airframe Parts

Part	Price	Core Exchange
Wing tip sights for Sukhoi	€215.00	
Yak 18T aileron bracket	€290.00	
Yak 18T door pins	€205.00	
Overhaul	Price	Core Exchange
Yak 50/52/18T undercarriage actuator overhaul. Please note there will be extra charges if we need to replace major items such as end cap; pistons; etc. But we will dismantle the old unit and provide a		
detailed quote with no obligation.	€480.00	
Yak undercarriage cockpit selector overhaul	€250.00	

General

		Core
Part	Price	Exchange
Flexible hoses. Our established price for all hoses to include crack		
test & x-ray of metal ends; machining to fit Aeroquip 303 hose;		
anodizing; assembly; pressure test; fireproof cover; EASA form 1.		
There are often two flexible hoses in a complete set which are		
permanent factory installed "pressurised" hose ends which we		
cannot replace. So we need to purchase complete new hoses from a		
specialised factory – cost of these is an additional €190.	€95.00/hose	
Engine lifting eye	€195.00	
Tools. Complete set of 11 necessary tools for all work on M14		
engines.	€525.00	645.00
Intake tubes, after OH	€65.00	€15.00
Engine mount rubbers. (16 for engine set). Each	€24.00	
Engine mounting bolt complete with stud, 2 nuts & 3 washers	€33.00	
Pushrod tube hoses, set of 18 @ €4 each	€72.00	
Pushrod tube clamps, set of 36 @ €3 each	€108.00	
M 14 P engine, after total zero-time overhaul. Please contact us for		
full details	€31,500.00	
M 14 PF engine, after total zero-time overhaul. Please contact us for	635 000 00	
full details	€35,000.00	
Zero-timed V-530 propeller	€7,600.00	
Shipping box for V-530 propeller	€300.00	
Treated wooden shipping crate	€300.00	
Legs and brackets for shipping crate	€180.00	
Unassembled shipping crate	€225.00	
Overhaul	Price	Core
	11166	Exchange
Engine overhaul to zero-time condition. Please contact us for full		
details	€26,500.00	
Overhaul of V-530 propeller	€4,750.00	
Remove and check cylinders	€1,650.00	
Engine dynonometer test. Full three hour test run on the		
dynonometer, with all results given to the customer	€1,500.00	
Preservation, long term	€560.00	
Preservation, short term	€260.00	
Chip detector cable sensor	€105.00	